

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_ *Film*

Customer : \_\_\_\_\_


Mold : \_\_\_\_\_ *1x1*

Width film : \_\_\_\_\_ *420 mm*

Diameter max : \_\_\_\_\_ *320 mm*

Core Ø Int : \_\_\_\_\_ *76 mm*

| Tolerances       |                          | Printing sign size  |
|------------------|--------------------------|---|
| Film type        | Tolerances per 1m lineal |  |
| Do not stretch   | -1 to 3 mm               |   |
| Normally Stretch | -2 to 5 mm               |   |
| Very soft        | -4 to -8 mm              | Colour: Black   |



FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIOUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_ *Film*

Customer : \_\_\_\_\_


Mold : 1x2

Width film : 420 mm

Diameter max : 320 mm

Core Ø Int : 76 mm

| Tolerances       |                          | Printing sign size |
|------------------|--------------------------|--------------------|
| Film type        | Tolerances per 1m lineal |                    |
| Do not stretch   | -1 to 3 mm               |                    |
| Normally Stretch | -2 to 5 mm               |                    |
| Very soft        | -4 to -8 mm              | Colour: Black      |



FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIOUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_


Customer : \_\_\_\_\_

Mold : 2x1



Width film : 420 mm

Diameter max : 320 mm

Core Ø Int : 76 mm

| Tolerances       |                          | Printing sign size  |
|------------------|--------------------------|---|
| Film type        | Tolerances per 1m lineal |  |
| Do not stretch   | -1 to 3 mm               |   |
| Normally Stretch | -2 to 5 mm               |   |
| Very soft        | -4 to -8 mm              | Colour: Black   |

Film



FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIOUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_

Film


Customer : \_\_\_\_\_


Mold : 2x2

Width film : 420 mm

Diameter max : 320 mm

Core Ø Int : 76 mm

| Tolerances       |                          | Printing sign size  |
|------------------|--------------------------|---|
| Film type        | Tolerances per 1m lineal |  |
| Do not stretch   | -1 to 3 mm               |   |
| Normally Stretch | -2 to 5 mm               |   |
| Very soft        | -4 to -8 mm              | Colour: Black   |



FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIOUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_

Customer : \_\_\_\_\_




Mold : 3x1

Width film : 420 mm

Diameter max : 320 mm

Core Ø Int : 76 mm

Film



| Tolerances       |                          | Printing sign size |
|------------------|--------------------------|--------------------|
| Film type        | Tolerances per 1m lineal |                    |
| Do not stretch   | -1 to 3 mm               |                    |
| Normally Stretch | -2 to 5 mm               | Colour: Black      |
| Very soft        | -4 to -8 mm              |                    |

FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIOUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_

Customer : \_\_\_\_\_

Mold : 3x2



Width film : 420 mm

Diameter max : 320 mm

Core Ø Int : 76 mm

| Tolerances       |                          | Printing sign size |
|------------------|--------------------------|--------------------|
| Film type        | Tolerances per 1m lineal |                    |
| Do not stretch   | -1 to 3 mm               |                    |
| Normally Stretch | -2 to 5 mm               | Colour: Black      |
| Very soft        | -4 to -8 mm              |                    |

Film



FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIOUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_


Customer : \_\_\_\_\_

Mold : \_\_\_\_\_ 4x1



Width film : \_\_\_\_\_ 420 mm

Diameter max : \_\_\_\_\_ 320 mm

Core Ø Int : \_\_\_\_\_ 76 mm

| Tolerances       |                          | Printing sign size  |
|------------------|--------------------------|---|
| Film type        | Tolerances per 1m lineal |  |
| Do not stretch   | -1 to 3 mm               |   |
| Normally Stretch | -2 to 5 mm               |   |
| Very soft        | -4 to -8 mm              | Colour: Black   |

Film



FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film

# Automatic thermoformer

## Print project

Serial number : \_\_\_\_\_

Customer : \_\_\_\_\_




Mold : 4x2

Width film : 420 mm

Diameter max : 320 mm

Core Ø Int : 76 mm

Film



| Tolerances       |                          | Printing sign size |
|------------------|--------------------------|--------------------|
| Film type        | Tolerances per 1m lineal |                    |
| Do not stretch   | -1 to 3 mm               |                    |
| Normally Stretch | -2 to 5 mm               | Colour: Black      |
| Very soft        | -4 to -8 mm              |                    |

FILM MANUFACTURER SHOULD REQUEST CONTAINER SAMPLES TO THE CUSTOMER TO CHECK MEASURES OF THE RADIOUS, WIDTH AND LENGTH OF THE CONTAINERS, AS WELL AS THE CHECKING OF THE EASY OPEN PLACEMENT.

That measures are the real in the machine mechanized - FRIMAQ is not responsible of possibles disturbances in the impressions caused by elongation or shrinkage caused by the quality of the film