

ACA INSTALLATION (Warming by steam)


WATER CONSUMPTION Liters/hour EVAPORATION AND FILLING ONLY

STEAM CONSUMPTION kg/hour 70/130
DE 2-4 BARES DE PRESIÓN

COMPRESSED AIR CONSUMPTION liters/minute 10
6 BARS PRESSURE

VOLTAGE 400 V 50/60 Hz
MAXIMUM POWER 3 Kw Kw
PHASE Nº. 3P+N+T
PLUG 5 POLES
PROTECTION _____
CABLE SECTION _____ mm2
MAXIMUM CONSUMPTION _____ Amp

VOLTAGE 230 V THREE -PHASE 50/60 Hz
MAXIMUM POWER _____ Kw
PHASE Nº. 3P+T
PLUG 4 POLES
PROTECTION _____
CABLE SECTION _____ mm2
MAXIMUM CONSUMPTION _____ Amp




Key ending in 1/2" female thread

STEAM OUTPUT

Ø170 mm Inside



PACKING ROOM



Turbine 500 m3/h
 Pressure 0
 Start up and stop
 from the machine.

EXTERIOR